

Y-Axis Flex Cable Install




Mini / Helix / Fibermark 8000 Series

Tools / Parts Required


- Phillips Head Screwdriver
- MT0106 Y-Axis Flex Cable (Mini / Fibermark)
- MT0751 Y-Axis Flex Cable (Helix)

Getting Started


1. Disconnect power.




2. Remove right-side panel.




3. Disconnect cable from X-Axis.




4. Disconnect cable from Control Board.




5. Remove cable.




6. Install cable.




7. Connect cable to Control Board.



8. Connect cable to X-Axis.



9. Install right-side panel.



10. Connect Power.

